BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

Boiler Chiller Interface

[Click here for English Release Note]

[Klicken Sie hier für die Softwareinformation auf Deutsch]

ABB STOTZ-KONTAKT GmbH
Eppelheimer Straße 82
69123 Heidelberg, Germany
Phone: +49 (0)6221 701 607
Email: info.bje@de.abb.com
www.abb.com/knx

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

Boiler Chiller Interface

Product name	Boiler Chiller Interface, MDRC
Product type	BCI/S 1.1.1
Order code	2CDG110222R0011
Latest change	ETS Application Update, 14/12/2021 Firmware Update, 29/07/2022

Current Status:

Product Type	Order Code	Website	ETS Application	Firmware
BCI/S1.1.1	2CDG110222R0011	Link	V1.1 Boiler Chiller Interface, Download here	V0.0.19 (available in ETS-App „ABB Firmware-Update 2.0")

NOTE:

We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

ETS APPLICATION

Product Type	Version	Release Date	Updates and Release Notes
BCI/S 1.1.1	1.1	14/12/2021	• Adaption of the temperature accuracy with DPT 9.001, the highest possible accuracy is now used. • Text corrections and adaptions of parameter & group object texts, alignment with user manual • Devices are now supported by the Update, Copy, Convert ETS App • Correction of the status displaying of the inputs on the keypad and in the i-bus Tool. Now always the physical condition of the input is shown, instead of the object. • It has been ensured that the fan relays and the relay output will be switched off (contact open) after the first connection of the device with the bus. Also, after every bus voltage recovery the relays are switched into their set position • Flawed option to surveillance the pump status receipt was removed (pump status can't be received via the bus) i-bus Tool: • Open/close button for the pump has been fixed • On/off button for the generator relay has been fixed
BCI/S 1.1.1	1.0a	01/2021	Adaption of the ETS catalog structure. No further changes compared to the previous version.
BCI/S 1.1.1	1.0	08/2018	Market introduction

FIRMWARE

Note: For firmware update please use ETS App „KNX Bus Update" (Engineering Guide)

Product Type	Version	Release Date	Updates and Release Notes
BCI/S 1.1.1	0.0.19	29/07/2022	• Improved stability operating system
BCI/S 1.1.1	0.0.17	14/12/2021	• Improved update stability • Optimization of transmission behavior in the event of KNX bus faults and high bus load.
BCI/S 1.1.1	0.0.13	08/2018	Market introduction

HAUS- UND GEBÄUDEAUTOMATION

Softwareinformation

Wärme-/Kälteerzeuger Interface

Produktname	Wärme-/Kälteerzeuger Interface, REG
Produkttyp	BCI/S 1.1.1
Bestellnummer	2CDG110222R0011
Aktuelle Version	ETS Applikationsupdate, 14/12/2021
	Firmware Update, 29/07/2022

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	ETS Applikation	Firmware
BCI/S1.1.1	2CDG110218R0011	Link	V1.1 Wärme-/Kälteerzeuger Interface Hier herunterladen	V0.0.19 (Verfügbar in ETS-App „ABB Firmware-Update 2.0”)

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

ETS APPLIKATION

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
BCI/S 1.1.1	1.1	• 14/12/2021	• Anpassung der Temperaturgenauigkeit bei DPT 9.001, es wird jetzt die größtmögliche Genauigkeit verwendet • Textkorrekturen und Anpassungen der Parameter-& Kommunikationsobjekttexte, Angleichung an Handbuch • Geräte werden von der Update, Copy, Convert App unterstützt • Korrektur der LED Anzeige der Eingänge auf der Folientastatur & im i-bus Tool. Es wird jetzt immer der physikalische Zustand des Eingangs angezeigt und nicht der des Objekts • Es wurde sichergestellt, dass Lüfter- & Zusatzrelais nach dem ersten Anschluss des Geräts an Bus ausschalten (Kontakt geöffnet). Zusätzlich werden bei Busspannungswiederkehr alle Relais aktiv in ihre Sollposition geschaltet. • Fehlerhafte Möglichkeit den Empfang des Pumpenstatus zu überwachen wurde entfernt (Pumpenstatus kann nicht über den Bus empfangen werden) i-bus Tool: • Öffnen/Schließen Schaltfläche der Pumpe wurde korrigiert • Ein/Aus Schaltfläche des Erzeugerrelais wurde korrigiert
BCI/S 1.1.1	1.0a	01/2021	Änderung der ETS-Katalogstruktur. Keine weiteren Änderungen gegenüber der Vorgängerversion.
BCI/S 1.1.1	1.0	08/2018	Markteinführung

FIRMWARE

Hinweis: Für Firmwareupdate verwenden Sie bitte die ETS App „KNX Bus Update" (Engineering Guide)

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
BCI/S 1.1.1	0.0.19	29/07/2022	• Verbesserte Stabilität Betriebssystem
BCI/S 1.1.1	0.0.17	14/12/2021	• Verbesserte Stabilität bei Updates • Optimierung Sendeverhalten bei KNX Busstörungen und hoher Bus-Last.
BCI/S 1.1.1	0.0.13	08/2018	Markteinführung