



Industrial IT Extended Automation System 800xA

PC Toolkit Library for Freelance V5.1-1 TC2 Temporary Correction Release Notes

Introduction

This document is the Temporary Correction Release Notes for PC Toolkit Library for Freelance V5.1-1 TC2.

The installation of this Temporary Correction is a general release.

It is of utmost importance that the installation procedure is followed. Installation of the Temporary Correction requires knowledge of installing and maintaining 800xA system installations. Contact ABB Support if there are any questions regarding the procedures or other issues concerning this correction.

This Temporary Correction requires that PC Toolkit Library for Freelance Version V5.1-1 is installed in the system.

ABB Automation GmbH

Postanschrift:
Postfach 93 02 09
D-60457 Frankfurt am Main

Besuchsanschrift:
Stierstädter Straße 5
D-60488 Frankfurt
Telefon +49 69 7930-4666
Telefax +49 69 7930-4499
Internet: <http://www.abb.com/de>

Sitz der Gesellschaft: Mannheim
Registergericht: Mannheim
Handelsregister: HRB 10111
USt-IdNr.: DE 814145656

Vorsitz des Aufsichtsrates:
Dr. Peter Terwisch
Geschäftsführung:
Daniel Huber (Vorsitz)
Hendrik Weiler

Bankverbindung:
UniCredit Bank AG München
SWIFT-Code HYVE DE MM XXX
Konto: 57 26 751
BLZ: 700 20270
IBAN DE15 7002 0270 0005 7267
51

Dealt with by
Lucas Lo Curto

Date
2014-01-23

Our ref.
3BDA035408-002

Fixed Problems

The table below lists the problems corrected in this Temporary Correction and briefly explains the fix or workaround for each problem.

Issue ID	Correction or Fix
<p>Long display call up times when HPHMI Alarm Indication Graphic Elements are used.</p> <p style="text-align: right;"><i>ID: F2K-GE-025</i></p>	<p>Fixed with TC2</p> <p>Functionality without TC2: The object PC Customizations was the place to setting up the alarm indication properties HPHMI Alarm Control Show Clear and HPHMI Alarm Control MaxPrio. (Object: Library Structure > Preferences & Customizations > PC Customizations, Aspect: HPHMI Settings)</p> <p>Functionality with TC2: The Graphic Element for the HPHMI Alarm indication is now referencing the object PC HPHMI Alarm Indication Settings. <i>In order to setting up the behavior of the Alarm Indication Graphic Element</i> edit the Expression Variables LimitPriorities, MaxPriority and ShowClearIndication of the Generic Element. (Object: Graphics Structure > Graphics Tools > PC High Performance HMI Elements > PC HP HMI Alarm Indication Settings, Aspect: PC HP HMI Alarm Indication Settings).</p>

Dealt with by
Lucas Lo Curto

Date
2014-01-23

Our ref.
3BDA035408-002

Installation

Install the Temporary Correction on one node of the System. Best on that node where the ABB software is stored.

1. If you are not logged on as a user with Administration privileges, log off and log on as a user with these privileges.
2. Create a new folder:
<installation disk>:\TemporaryCorrections\PC TKL for Freelance 5.1-1 TC2
3. Unzip the Temporary Correction file to the folder created in step 2 above.
4. Load the temporary correction by open the AFW file(s) in the Import/Export wizard (or double click the AFW file within the Windows Explorer).
5. In the Import / Export Wizard click Import All in the menu bar. If a "Replace Existing Object" dialog occurs, set the "Apply to all" checkbox and click the Yes button.

Support

Contact ABB technical support for assistance in problem reporting.