
BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

Busch-free@homePanel 7"/
ABB-free@homeTouch 7"

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

Busch-Jaeger Elektro GmbH
Freisenbergstr. 2
58513 Lüdenscheid
Telefon: 02351 956-1600
Telefax: 02351 956-1700
E-Mail: info.bje@de.abb.com
www.abb.com/knx

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

ABB-free@homeTouch 7"

Product name	ABB-free@homeTouch 7"
Product type	83221AP-XXX, DP7-S-XXX
Order code	2CKA008300A0353, 2CKA008300A0354, 2CKA008300A0356, 2CKA008300A0357, 2CKA008300A0359, 2CKA008300A0360, 2TMA210050B0006, 2TMA210050W0017
Latest change	Firmware Update, 03/01/2024

Current Status:

Product Type	Order Code	Website	Firmware
83221AP-611	2CKA008300A0353	Link	<u>V1.57</u>
83221AP-625	2CKA008300A0354	Link	
DP7-S-611	2CKA008300A0356	Link	
DP7-S-625	2CKA008300A0357	Link	
DP7-S-611-515	2CKA008300A0359	Link	
DP7-S-625-515	2CKA008300A0360	Link	
DP7-S-625-02	2TMA210050B0006	Link	
DP7-S-611-02	2TMA210050W0017	Link	

Kommentiert [SS1]: Bitte entsprechend anpassen und die Tabelle bei neuen Einträgen erweitern!

NOTE:
We recommend ensuring that devices are always installed and operating using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

FIRMWARE

Product Type	Version	Release Date	Updates and Release Notes
DP7-S-6XX	1.57	03.01.2024	Bugfix: Fixes an error that can occur during restart
DP7-S-6XX	1.56	21.01.2022	<ul style="list-style-type: none">• New Feature: New fan icon• Bugfix: Bugfixes in combination with secure @home• Bugfix: Fixes a bug with the status display of blind groups• Bugfix: General stability improvements
DP7-S-6XX	1.50	05.08.2020	<ul style="list-style-type: none">• New Feature: Support for home appliances from Miele and B/S/H/• New Feature: Support for the Split Unit Gateway• New Feature: Additional Icons for Scenes
DP7-S-6XX	1.42	08.10.2018	<ul style="list-style-type: none">• New Feature: Support for Busch-secure@home• New Feature: Temperature can be set to Fahrenheit• New Feature: Sonos players now indicate whether they are part of a group• New Feature: Door calls can now be linked to a scene• Bugfix: Bugfix for issues with blind groups• Bugfix: Various stability improvements
DP7-S-6XX	1.33	29.03.2018	<ul style="list-style-type: none">• Bugfix: Fixes a bug in version 1.31 that caused problems with some Panels
DP7-S-6XX	1.31		<ul style="list-style-type: none">• New Feature: Visualization of the window status (shows automatically when window contacts are installed)• New Feature: Visualization of weather station data (shows automatically when weather station is installed)• New Feature: Support for Sonos Controls (the speaker control must be placed manually on the panel)• New Feature: Schedules and Actions can be activated / deactivated from the panel (the Schedule must be placed manually on the panel, one Schedule occupies one control frame)• New Feature: Support for "trigger" actuators• New Feature: New icons for scenes• New Feature: New icons to visualize actuators in forced position

Kommentiert [SS2]: Datum weiß ich nicht!

HAUS- UND GEBÄUDEAUTOMATION

Softwareinformation

Busch-free@homePanel 7"

Produktname	Busch-free@homePanel 7"
Produkttyp	83221AP-XXX
Order code	2CKA008300A0353, 2CKA008300A0354,
Aktuelle Version	Firmware Update, 03/01/2024

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	Firmware
83221AP-611	2CKA008300A0353	Link	<u>V1.57</u>
83221AP-625	2CKA008300A0354	Link	

Kommentiert [SS3]: Bitte entsprechend anpassen und die Tabelle bei neuen Einträgen erweitern!

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

FIRMWARE

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
83221AP-6XX	1.57	03.01.2024	• Bugfix: Behebt einen Fehler der während eines Neustarts auftreten kann
83221AP-6XX	1.56	21.01.2022	• Neues Feature: Neues Ventilator Icon • Bugfix: Bugfixes bei der Verbindung mit secure @home • Bugfix: Behebt einen Fehler bei der Statusanzeige von Jalousiegruppen • Bugfix: Generelle Stabilitätsverbesserung
83221AP-6XX	1.50	05.08.2020	• Neues Feature -Unterstützung für Hausgeräte von Miele und B/S/H/' • Neues Feature: Unterstützung für das Split Unit Gateway • Neues Feature: Zusätzliche Szenen Icons

83221AP-6XX	1.42	08.10.2018	<ul style="list-style-type: none"> • Neues Feature: Unterstützung für Busch-secure@home • Neues Feature: Unterstützung für Temperaturanzeige in Fahrenheit • Neues Feature: Indikation bei Sonos Playern, wenn diese in einer Gruppe sind • Neues Feature: Türrufe können jetzt mit Szenen verknüpft werden • Bugfix: Fehlerbehebung bei Jalousiegruppen • Bugfix: Diverse Stabilitätsverbesserungen
83221AP-6XX	1.33	29.03.2018	<ul style="list-style-type: none"> • Bugfix: Behebt einen Fehler der Version 1.31, der bei einigen Panels zu Problemen führte
83221AP-6XX	1.31		<ul style="list-style-type: none"> • Neues Feature: Visualisierung des Fenster Status (automatisch bei vorhandenen Fensterkontakten) • Neues Feature: Visualisierung der Wetterstationsdaten (automatisch bei vorhandener Wetterstation) • Neues Feature: Unterstützung für Sonos Controls (der gewünschte Speaker muss manuell auf dem Panel platziert werden) • Neues Feature: Zeitprogramme und Aktionen können vom Panel aus aktiviert/deaktiviert werden (das gewünschte Zeitprogramm muss manuell auf dem Panel platziert werden; ein Zeitprogramm belegt eine Schaltfläche) • Neues Feature: Unterstützung für „Trigger“ Aktoren • Neues Feature: Neue Icons für Szenen • Neues Feature: Neue Icons um Aktoren in Zwangsstellung zu visualisieren

Kommentiert [SS4]: Datum weiß ich nicht!