


RELEASE NOTE - JUNE 17, 2022

PCM600 version 2.11 Hotfix 20220617

Release of hotfix for Protection and Control IED Manager PCM600 version 2.11



Document Number: 1MRS228225



Introduction

A hotfix package for Protection and Control IED Manager PCM600 version 2.11 has been released. We highly recommend the installation of this hotfix 20220617 when using PCM600 version 2.11.

Please refer next section for more details about improvements and corrections done in the hotfix.



Improvements and corrections

Improvements and corrections:

- Fix for cases where communication configuration with SMV did not work as expected for certain IED families.
- Inconsistencies with GOOSE communication after PCM600 project migration corrected.
- Improved robustness of Communication connection.
- Improved robustness of Update Manager with installed language add-ons.

ABB Oy Distributed Solutions P.O. Box 699 FI-65101 Vaasa, Finland Phone: +358 10 22 11

abb.com/mediumvoltage

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document. We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2022 ABB All rights reserved

- Improved handling of high DPI settings.
- Improved handling of measurement labels in Graphical Display Editor.
- Improved robustness in interoperability with third party IEDs.
- Fix for error scenarios where configuring some IEDs failed when example configuration (*.pcmi) option is selected in IED configuration wizard.

This hotfix includes also the previously released hotfix for PCM600 version 2.11:

• PCM600 2.11 Hotfix 20220318.exe

The hotfix 20220617 for PCM600 version 2.11 is available via the PCM600 Update Manager and PCM600 Product Page. It contains the following file:

• PCM600 2.11 Hotfix 20220617.exe

We recommend the installation of this hotfix 20220617 when using PCM600 version 2.11.

For more information, please contact your local ABB representative.

ABB constantly examines both operational and new software to identify possible faults or product improvements, issuing hotfixes where appropriate. We apologize for any inconvenience the identified faults have caused.

Known limitations

Avoid using F3 key when working with data grid in PCM600 version 2.11 and hotfixes.

Gaurav Srivastav Global Product Manager

ABB

ABB Oy Medium Voltage Products, Distribution Solutions P.O. Box 699 FI-65101 VAASA, Finland Phone +358 10 22 11

abb.com/mediumvoltage

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document. We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2022 ABB All rights reserved