

RELEASE NOTE - NOV 25, 2022

PCM600 version 2.11Hotfix 20221125

Release of hotfix for Protection and Control IED Manager PCM600 version 2.11



Document Number: 1MRS228245

Revision: A



Introduction

A hotfix package for Protection and Control IED Manager PCM600 version 2.11 has been released. We strongly recommend the installation of this hotfix 20221125 when using PCM600 version 2.11.

Please refer next section for more details about improvements and corrections done in the hotfix.

Improvements and corrections



Improvements and corrections:

- Improved robustness of Communication Connect
- Improved handling of subnetwork name on import of SCD
- Fixed error scenario on import of archived PCM600 project (*. PCMA)
- Improved handling of GOOSE client mapping on read
- Improved robustness with SCD export via Command Line Interface (CLI)

ABB Oy Distributed Solutions P.O. Box 699 FI-65101 Vaasa, Finland Phone: +358 10 22 11

abb.com/mediumvoltage

We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB Oy does not accept any responsibility whatsoever for potential errors or possible lack of information in this document.

We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB Oy. Copyright© 2022 ABB All rights reserved

• Better usages of Windows 11

This hotfix includes also the previously released hotfix for PCM600 version 2.11:

- PCM600 2.11 Hotfix 20220318.exe
- PCM600 2.11 Hotfix 20220617.exe
- PCM600 2.11 Hotfix 20220923.exe

The hotfix 20221125 for PCM600 version 2.11 is available via the PCM600 Update Manager and PCM600 Product Page. It contains the following file:

PCM600 2.11 Hotfix 20221125.exe

We recommend the installation of this hotfix 20221125 when using PCM600 version 2.11.

For more information, please contact your local ABB representative.

ABB constantly examines both operational and new software to identify possible faults or product improvements, issuing hotfixes where appropriate. We apologize for any inconvenience the identified faults have caused.

Known limitations

Avoid using F3 key when working with data grid in PCM600 version 2.11 and hotfixes.

Gaurav Srivastav

Global Product Manager

ABB