

RELION® PROTECTION AND CONTROL

TISSUES Implementation Conformance Statement (TICS)

REX640 IEC 61850 interface



| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 1/9 |

Contents

| | |
|--|----------|
| 1. Introduction | 3 |
| 1.1. Document information..... | 3 |
| 1.2. Safety Information..... | 3 |
| 2. Mandatory Edition 2 Tissues..... | 4 |
| 2.1. Part 6..... | 4 |
| 2.2. Part 7-1..... | 5 |
| 2.3. Part 7-2 | 6 |
| 2.4. Part 7-4 | 6 |
| 2.5. Part 8-1 | 9 |

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 2/9 |

1. Introduction

This document provides the Tiger platform Technical Issues Conformance Statement (TICS). According to the UCA IUG QAP the tissue conformance statement is required to perform a conformance test and is referenced on the certificate. For more details to technical issues check following official web page: <http://www.tissues.iec61850.com>.

1.1. Document information

| Revision | Date | Note |
|----------|------------|-------------|
| A | 20.4.2018 | REX640 PCL1 |
| B | 14.11.2022 | REX640 PCL4 |

Applicability

This manual is applicable to all REX640 Protection and Control IED versions mentioned in document Revision History above or newer versions if document update is not required.

1.2. Safety Information

There are safety warnings and notes in the following text. They are in a different format to distinguish them from normal text.

Safety warning

The safety warnings should always be observed. Non-observance can result in death, personal injury, or substantial damages to property. Guarantee claims might not be accepted when safety warnings are not respected. They look like below:



Do not make any changes to the REX640 configuration unless you are familiar with the REX640 and its configuration tool. This might result in disoperation and loss of warranty.

Note

A note contains additional information worth noting in the specific context, and looks like below:



The selection of this control mode requires caution, because operations are allowed both from the HMI and remotely.

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 3/9 |

2. Mandatory Edition 2 Tissues

2.1. Part 6

| ID | Description | Implemented |
|-----|--|-------------|
| 658 | Tracking related features | n/a |
| 663 | FCDA element cannot be a "functionally constrained logical node" | Y |
| 668 | Autotransformer modeling | n/a |
| 687 | SGCB ResvTms | n/a |
| 719 | ConfDataSet - maxAttributes definition is confusing | Y |
| 721 | Log element name | n/a |
| 768 | bType VisString65 is missing | n/a |
| 779 | object references | Y |
| 788 | SICS S56 from optional to mandatory | n/a |
| 789 | ConfLdName as services applies to both server and client | n/a |
| 804 | valKind and IED versus System configuration | n/a |
| 806 | Max length of log name inconsistent between -6 and -7-2 | n/a |
| 807 | Need a way to indicate if "Owner" present in RCB | n/a |
| 822 | Extension of IED capabilities | Y |
| 823 | ValKind for structured data attributes | Y |
| 824 | Short addresses on structured data attributes | n/a |
| 825 | Floating point value | n/a |
| 845 | SGCB ResvTms | n/a |
| 853 | SBO and ProtNs | Y |
| 855 | Recursive SubFunction | n/a |
| 856 | VoltageLevel frequency and phases | n/a |
| 857 | Function/SubFunction for ConductingEquipment | n/a |
| 886 | Missing 8-1 P-types | n/a |

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 4/9 |

| ID | Description | Implemented |
|-------------|---|-------------|
| 901 | tServices as AP or as IED element | Y |
| Y936 | SupSubscription parameter usage is difficult | n/a |
| 1147 | tServices – FileHandling not consistent with 7-2 | Y |
| 1175 | IPv6 address lowercase only | n/a |
| 1185 | Valkind value Conf for EX FC data | Y |
| 1284 | SCSM mapping may require a communication section in an ICD file | Y |
| 1328 | Limitation on the size fo data type templates identifiers | Y |
| 1395 | Client LN attributes | Y |
| 1402 | Extref during engineering | n/a |
| 1415 | SICS-S110 IID import mandatory for Edition2 | n/a |
| 1419 | Support of IdName on other IEDs | Y |
| 1444 | Need to support fixed and SCT controlled datasets | n/a |
| 1445 | ConfReportControl and a fixed ReportSettings | n/a |
| 1450 | originalSclXxx computation rules | Y |
| 1485 | Need to supercede Tissue 1398 to clarify SCT behavior | n/a |

2.2. Part 7-1

| ID | Description | Implemented |
|-------------|--|-------------|
| 828 | Data model namespace revision IEC 61850-7-4:2007[A] | Y |
| 948 | Enumeration (String values format) | Y |
| 1151 | simulated GOOSE disappears after 1st appearance when LPHD.Sim = TRUE | Y |
| 1396 | The use and configuration flow of LGOS and LSVS is unclear | n/a |
| 1447 | Restriction on ENUMtypes in SCL | Y |
| 1457 | Multiple DOI nodes with the same name | Y |

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 5/9 |

| ID | Description | Implemented |
|-------------|---|-------------|
| 1468 | Re-use DO from other LN | Y |
| 1491 | CmdBlk blocks itself? | Y |
| 1495 | GetVariableAccessAttributes error code Return MMS error access/object-non-existent if the object does not exist | Y |

2.3. Part 7-2

| ID | Description | Implemented |
|-------------|---|-------------|
| 697 | persistent command / PulseConfig | Y |
| 698 | Wrong case is BAC.dB attribute | n/a |
| 711 | blkEna freeze data update while setting its quality to operatorblocked | n/a |
| 722 | Units for 'h' and 'min' not in UnitKind enumeration. | Y |
| 919 | Presence Condition for sVC | n/a |
| 925 | Presence of i or f attribute - Problem with writing | n/a |
| 926 | Presence Conditions within RangeConfig | Y |
| 954 | Data attributes with FC=CF should have trgOp=dchg | Y |
| 1078 | CMV.t update if rangeAng changed | n/a |
| 1565 | db = 0 behaviour | n/a |
| 1578 | dataAttribute NameSpace content | Y |

2.4. Part 7-4

| ID | Description | Implemented |
|------------|---|-------------|
| 671 | mistake in definition of Mod & Beh | Y |
| 674 | CDC of ZRRC.LocSta is wrong | n/a |
| 675 | SIML LN | Y |
| 676 | Same data object name used with different CDC | n/a |

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 6/9 |

| ID | Description | Implemented |
|------------|---|--------------------|
| 677 | MotStr is used with different CDC in PMMS and SOPM LN classes | n/a |
| 679 | Remove CycTrMod Enum | n/a |
| 680 | SI unit for MHYD.Cndct | n/a |
| 681 | Enum PIDAlg | n/a |
| 682 | ANCR.ParColMod | n/a |
| 683 | Enum QVVR.IntrDetMth | n/a |
| 685 | Enum ParTraMod | Y |
| 686 | New annex H - enums types in XML | Y |
| 694 | Data object CmdBlk | n/a |
| 696 | LSVS.St (Status of subscription) | n/a |
| 712 | interpretation of quality operatorBlocked | Y |
| 713 | DO Naming of time constants in FFIL | n/a |
| 714 | Enums for ShOpCap and SwOpCap | n/a |
| 715 | RBDR.ChNum1 | n/a |
| 716 | TAXD text for condition | n/a |
| 724 | ANCR.Auto | n/a |
| 725 | Loc in LN A-group | n/a |
| 734 | LLN0.OpTmh vs. LPHD.OpTmh | n/a |
| 735 | ISAF.Alm and ISAF.AlmReset | n/a |
| 736 | PFSign | n/a |
| 742 | GAPC.Str, GAPC.Op and GAPC.StrVal | Y |
| 743 | CCGR.PmpCtl and CCGR.FanCtl | n/a |
| 744 | LN STMP, EEHealth and EEName | n/a |
| 772 | LPHD.PwrUp/PwrDn shall be transient | Y |
| 773 | Loc, LocKey and LocSta YPSH and YLTC | n/a |
| 774 | ITCI.LocKey | n/a |
| 775 | KVLV.ClsLim and OpnLim | n/a |
| 776 | LPHD.OutOv/InOv and LCCH.OutOv/InOv | n/a |

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 7/9 |

| ID | Description | Implemented |
|-------------|---|-------------|
| 800 | Misspelling in CSYN | n/a |
| 802 | CCGR and Harmonized control authority | Y |
| 808 | Presence condition of ZMOT.DExt and new DOs | n/a |
| 831 | Setting of ConfRevNum in LGOS | n/a |
| 838 | Testing in Beh=Blocked | Y |
| 844 | MFLK.PhPiMax, MFLK.PhPiLoFil, MFLK.PhPiRoot DEL->WYE | n/a |
| 849 | Presence conditions re-assessing in case of derived statistical calculation | n/a |
| 877 | QVUB -settings should be optional | n/a |
| 908 | ARIS.StrSeq – transient | Y |
| 909 | Remove ANCR.ColOpR and ColOpL | n/a |
| 912 | Clarification of PwrRtg/VARtg | n/a |
| 920 | Resetable Counter is NOT resetable | Y |
| 932 | Rename AVCO.SptVol to AVCO.VolSpt | n/a |
| 933 | Presence of LCCH.RedFerCh and RedRxCnt | n/a |
| 939 | Change CDC for ANCR.FixCol | Y |
| 991 | LGOS: GoCBRef (as well as LSVS.SvCBRef) should be mandatory | n/a |
| 1007 | PTRC as fault indicator - Update of description required | Y |
| 1044 | TapChg in AVCO | n/a |
| 1077 | Rename DOnames within LTIM | Y |
| 1256 | New DO for LTIM to set time “manually” | n/a |
| 1331 | Mod, Beh, and Health with q=TEST, client can't receive their states | Y |
| 1426 | Add two DO for leap seconds in LTIM | n/a |
| 1456 | Annex A and Mod/Beh/Health | Y |
| 1568 | ISAF.AlmReset -> transient | n/a |

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 8/9 |

2.5. Part 8-1

| ID | Description | Implemented |
|------|--|-------------|
| 770 | Goid type mismatch 18.1.1 and 18.1.2.5.2 | Y |
| 784 | Tracking of control | n/a |
| 817 | Fixed-length GOOSE float encoding | Y |
| 827 | Mandatory ACSI services (Part of 7-2 TISSUE resolution) | Y |
| 834 | File dir name length 64 | Y |
| 951 | Encoding of Owner attribute | n/a |
| 1040 | More associate error codes | n/a |
| 1178 | Select Response+ is non-null value | Y |
| 1324 | The response- for DeleteNamedVariableList is not defined | n/a |
| 1345 | Fixed-length GOOSE ASN.1 length encoding | n/a |
| 1441 | Optional fields in buffered reports | Y |
| 1442 | Journal variableTag for ReasonCode | n/a |
| 1453 | Purge buffer on write to BRCB | Y |
| 1495 | GetVariableAccessAttributes error code | Y |
| 1500 | the response for DeleteNamedVariableList with a non-existent LN is not specified | n/a |
| 1626 | PICS for Information Report is incorrect | Y |

| PRODUCT | PRODUCT VERSION | DOCUMENT ID. | REV. | LANG. | PAGE |
|---------|-----------------|--------------|------|-------|------|
| REX640 | PCL4 | 1MRS759027 | B | en | 9/9 |