




SACE Emax 2 - Tmax XT

Otturatori di sicurezza - E1.2 - XT7 - XT7M
Safety shutters - E1.2 - XT7 - XT7M
Sicherheitstrennklappen - E1.2 - XT7 - XT7M
Obturbateurs de sécurité - E1.2 - XT7 - XT7M
Obturadores de seguridad - E1.2 - XT7 - XT7M


E1.2 - XT7 - XT7M




1



2



3



OK 2°

A4

1

2

3

A4

- Eseguire una prova manuale del funzionamento degli otturatori spingendo manualmente le slitte

- Perform a manual test on the operation of the shutters, pushing the slides manually

- Eine manuellen Funktionstest der Trennklappen ausführen, indem man die Gleitslitten von Hand drückt

- Effectuer un essai final du fonctionnement des obturateurs, en poussant manuellement les coulisseaux

- Efectuar una prueba manual del funcionamiento de las pantallas, empujando manualmente las guías

1,5 Nm

16,25

12

1

2

3

C

B

E

D

For more information please contact:

ABB S.p.A.
Via Pescaria, 5
24123 Bergamo - Italy
Phone: +39 035 395 111

© Copyright 2013-2019 ABB. All rights reserved.
www.abb.com

