



SACE Tmax XT

KLC-A STI, RONIS 1104, Kirk - XT7

XT7



A CURA DEL CLIENTE
AT CUSTOMER'S EXPENSE
ZU LASTEN DES KUNDEN
A LA CHARGE DU CLIENT
A CARGO DEL CLIENT
由客户承担



STI
KIRK

1

1

1

1

1

2

RONIS

1


1

1


1

1



2





STI
KIRK





RONIS



Posizione camma per montaggio, chiave non estraibile
Cam position for assembly, key not removable
Montagenockenstellung, schlüssel nicht abziehbar
Position came pour montage, clé non débrochable
Posición leva para montaje, llave no extraíble
装配时的凸轮位置, 不可拔取的钥匙位置




Posizione chiave estraibile
Position where the key can be removed
Stellung schlüssel abziehbar
Position clé débrochable
Posición llave extraíble
可拔取的钥匙位置




4

For F only 5




For F only




6

For F only




7

For W only 8




For W only




9

For W only 10




For W only




11

For W only




12



For W only




13

For W only









17

For F - W only 18

For F - W only



Posizione chiave non estraibile - blocco non attivo
 Key in non-removable position - lock not activated
 Position Schlüssel nicht abziehbar - Verriegelung nicht aktiv
 Position clé non extractible - verrouillage non actif
 Posición llave no extraíble - bloqueo inactivo
 不可拔取的钥匙位置 - 未激活锁定



Posizione chiave estraibile - blocco attivo
 Key in removable position - lock activated
 Position Schlüssel abziehbar - Verriegelung aktiv
 Position clé extractible - verrouillage actif
 Posición llave extraíble - bloqueo activo
 可拔取的钥匙位置 - 激活锁定