Product change notification Remove EAC logo of MCB, MCBL, MLBL

PCN Details			
PCN Document No.	1SFC151072K0201	Date of PCN:	2022 Q4
PCN issued by:	Hunter-JianQi Lin	PCN valid as of:	2022 Q4
Product Manager:	Pavlo Tkachenko	Obsolescence Date:	
	Maggie-Huanwen Ao		
R&D Manager:	Doree-MingShi Fan	Change Date:	2022 Q4
	Jay-JieJun Lv		
Products impacted:	MCB, MCBL, MLBL series		
Impact on Form/Fit/Func-	[X] Form [] Fit [X]	Impact on reliabil-	[]Y [X]N
tion:	Fctn	ity:	


Dear Valued Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and our processes.

Description of Change

Remove the EAC logo from all labels and makings of MCB, MCBL, MLBL. Example:

Before changed



After changed

Before changed 1SFA611621R1071 QTY 10 MLBL-07R MILDL-U/IN MODULAR LED BLOCK LED LANPABLOCK LED BLOC DE LANPAR LED BLOCUE DE LANPAR LED BLOCUE DE LANPAR LED LANPE BLOCK STATES STATES US:NLBL—07R SE: FR: ES: ES: IT: DE: PL: RL: RL: CN:10090109 CE 🏽 💁 🔣 7320500372852 蔥 18.03.05 Made in China ABB AB, Control Products SE-72161 Västerås Sweden ABB新会低压开关有限公司 广东省江门市新会区 今古洲工业开发区 合格 n bb.com/lowvoltage

After changed



Customer Impact of Change and Recommended Action

The label and marking looks different.

Reason for Change

EAC of MCB, MCBL and MLBL is expired. And there is no intention to update it.

Product Identification

See images above.

_