

—

GPG BUILDING AUTOMATION, 09.07.2018

# Technical Bulletin

## Application unit AB/S 1.1

### Subject

AB/S 1.1 Version Logic time 200EA/1.4 – Application under ETS4/5 and Windows 10

### Symptoms

Framework 1.1 can not be installed under Windows 10.

Higher versions are already installed and the installation of Framework 1.1 is not supported.

### Cause

Windows has discontinued support for Framework 1.1 on Windows 10.

Windows 10 does not support Framework 1.1 applications.

### Action

Installing of an additional virtual machine under Windows 10.

Alternative system software Windows 7.

Replacement in ABL/S 2.1 (conversion AB/S in ABL/S is possible)

No further measurements planned for the application under Windows 10.

The product AB/S 1.1 has been discontinued since 2007. Replacement type is ABL/S 2.1.

| Product Type | Product ID      | Additional Info (part ID, serie nr.) |
|--------------|-----------------|--------------------------------------|
| AB/S 1.1     | GHQ6310030R0111 |                                      |
| 6198/10      | 2CKA006198A0071 |                                      |

**For more information please contact:**

ABB STOTZ-KONTAKT GmbH

PM Application Engineering

Phone: : +49 6221 701434

Email: [knx.marketing@de.abb.com](mailto:knx.marketing@de.abb.com)

GPG BUILDING AUTOMATION, 09.07.2018

# Technische Mitteilung

## Applikationsbaustein AB/S 1.1

### Thema

AB/S 1.1 Version Logic time 200EA/1.4 – Anwendung unter ETS4/5 und Windows 10.

### Symptome

Framework 1.1 kann nicht unter Windows 10 installiert werden.

Höhere Versionen sind bereits installiert und die Installation von Framework 1.1 wird nicht unterstützt.

### Ursache

Windows hat den Support für Framework 1.1 unter Windows 10 eingestellt.

Windows 10 unterstützt keine Framework 1.1 Anwendungen.

### Maßnahme

Installation einer zusätzlichen virtuellen Maschine unter Windows 10.

Alternatives Betriebssystem Windows 7.

Austausch in ABL/S 2.1 (Konvertierung AB/S in ABL/S ist möglich).

Keine weitere Maßnahmen zur Ertüchtigung für die Anwendung unter Windows 10 geplant.

Das Produkt AB/S 1.1 ist seit 2007 abgekündigt. Ersatztyp ist ABL / S 2.1.

| Produkt Typ | Produkt ID      | Zusatzinfo (Art-Nr., Serie Nr.) |
|-------------|-----------------|---------------------------------|
| AB/S 1.1    | GHQ6310030R0111 |                                 |
| 6198/10     | 2CKA006198A0071 |                                 |

Für weiteren Informationen, kontaktieren Sie bitte:

ABB STOTZ-KONTAKT GmbH

PM Application Engineering

Telefon: : +49 6221 701434

E-Mail: [knx.marketing@de.abb.com](mailto:knx.marketing@de.abb.com)