



BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

LED-Dimmer 315 W/VA

[Click here for English Release Note](#)

[Klicken Sie hier für die Softwareinformation auf Deutsch](#)

Busch-Jaeger Elektro GmbH
Freisenbergstraße 2
58513 Lüdenscheid, Germany
Phone: +49 (0)2351 956 1600
Email: info.bje@de.abb.com
www.busch-jaeger.de

We reserve the right to make technical changes or modify the contents of this document without prior notice. ABB shall in no case be liable under, or in connection with, the document towards any person or entity, to which the document has been made available, in view of any damages or losses - irrespective of the legal grounds.

In particular ABB shall in no event be liable for any indirect, consequential or special damages, such as – but not limited to – loss of profit, loss of revenue, loss of earnings, cost of capital or cost connected with an interruption of business. With regard to purchase orders, the agreed particulars shall prevail. © Copyright 2020 ABB. All rights reserved

BUILDING AND HOME AUTOMATION SOLUTIONS

Release Note

LED-Dimmer

Product name	LED-Dimmer 2 x 315 W LED-Dimmer 4 x 315 W LED-Dimmer 6 x 315 W
Product type	UD/S2.315.11, UD/S2.315.1 UD/S4.315.11, UD/S4.315.1 UD/S6.315.11, UD/S6.315.1
Order code	2CKA006197A0052, 2CKA006197A0053 2CKA006197A0056, 2CKA006197A0057 2CKA006197A0060, 2CKA006197A0061
Latest change	Firmware Update, 27/08/2021

Current Status:

Product Type	Order Code	Website	ETS Application	Firmware
UD/S2.315.11 UD/S2.315.1	2CKA006197A0052 2CKA006197A0053	Link	V1.1 Dimmer/1.1 Download	V0.1.8 Download
UD/S4.315.11 UD/S4.315.1	2CKA006197A0056 2CKA006197A0057	Link	V1.1 Dimmer/1.1 Download	V0.1.8 Download
UD/S6.315.11 UD/S6.315.1	2CKA006197A0060 2CKA006197A0061	Link	V1.1 Dimmer/1.1 Download	V0.1.8 Download

NOTE:

We recommend ensuring that devices are always installed and operated using the latest firmware and software versions. Claims for defects or damages due to the use of software or firmware versions that have not been kept up to date will not be accepted.

ETS APPLICATION

Product Type	Version	Release Date	Updates and Release Notes
UD/S2.315.2.11 UD/S2.315.2.1 UD/S4.315.2.11 UD/S4.315.2.1 UD/S6.315.2.11 UD/S6.315.2.1	1.1	08/2019	Function Dimmer, Feedback and error messages, sending of communication object „Error diagnosis“ fixed
	1.0	06/2018	Market introduction

FIRMWARE

Note: For firmware update please use ETS App „ABB Firmware Update 2.0“

Product Type	Version	Release Date	Updates and Release Notes
UD/S2.315.2.11 UD/S2.315.2.1 UD/S4.315.2.11 UD/S4.315.2.1 UD/S6.315.2.11 UD/S6.315.2.1	0.1.8	09/2021	Function Dimmer, Faults, Dimming value at KNX return of voltage „As prior to failure“ fixed.
	0.1.7	05/2021	Function Dimmer, Scenes, Dimmer Scene x, „Stored scene values overwrite at download“ fixed.
	0.1.6	12/2020	Function Dimmer, Basic settings „Transistion behaviour logarithmic“ fixed
	0.1.5		Not published
	0.1.4	02/2019	Common functions, Delay: Function at data type 1-bit switching fixed
	0.1.3	06/2018	Market introduction

HAUS- UND GEBÄUDEAUTOMATION

Softwareinformation

LED-Dimmer

Produktname	LED-Dimmer 2 x 315 W LED-Dimmer 4 x 315 W LED-Dimmer 6 x 315 W
Produkttyp	UD/S2.315.11, UD/S2.315.1 UD/S4.315.11, UD/S4.315.1 UD/S6.315.11, UD/S6.315.1
Bestellnummer	2CKA006197A0052, 2CKA006197A0053 2CKA006197A0056, 2CKA006197A0057 2CKA006197A0060, 2CKA006197A0061
Aktuelle Version	Firmware-Update, 27/08/2021

Aktueller Status:

Produkttyp	Bestellnummer	Webseite	ETS Applikation	Firmware
UD/S2.315.11 UD/S2.315.1	2CKA006197A0052 2CKA006197A0053	Link	V1.1 Dimmer/1.1 Download	V0.1.8 Download
UD/S4.315.11 UD/S4.315.1	2CKA006197A0056 2CKA006197A0057	Link	V1.1 Dimmer/1.1 Download	V0.1.8 Download
UD/S6.315.11 UD/S6.315.1	2CKA006197A0060 2CKA006197A0061	Link	V1.1 Dimmer/1.1 Download	V0.1.8 Download

BEMERKUNG:

Wir empfehlen Ihnen, immer die aktuellste Softwareversion zu installieren. Ansprüche aus Mängeln oder Schäden aufgrund einer nicht aktuell gehaltenen Softwareversion können nicht geltend gemacht werden.

ETS APPLIKATION

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
UD/S2.315.2.11 UD/S2.315.2.1 UD/S4.315.2.11 UD/S4.315.2.1 UD/S6.315.2.11 UD/S6.315.2.1	1.1	08/2019	Funktion Dimmer, Rück- und Fehlermeldungen, Aussenden des Kommunikationsobjektes „Fehlerdiagnose“ korrigiert
	1.0	06/2018	Markteinführung

FIRMWARE

Hinweis: Für Firmwareupdates verwenden Sie bitte die ETS App „BJE Firmware Update 2.0“

Produkttyp	Version	Erscheinungsdatum	Updates und Release Notes
UD/S2.315.2.11 UD/S2.315.2.1 UD/S4.315.2.11 UD/S4.315.2.1 UD/S6.315.2.11 UD/S6.315.2.1	0.1.8	09/2021	Funktion Dimmer, Störungen, Dimmwert bei KNX-Spannungswiederkehr „wie vor Ausfall“ korrigiert
	0.1.7	05/2021	Funktion Dimmer, Szene, „gespeicherte Szene bei Download überschreiben“ korrigiert
	0.1.6	12/2020	Funktion Dimmer, Grundeinstellung „Übergangsverhalten logarithmisch“ korrigiert
	0.1.5		Nicht veröffentlicht
	0.1.4	02/2019	Allgemeine Funktionen, Verzögerung: Funktion bei Datentyp „1 Bit Schalten“ korrigiert
	0.1.3	06/2018	Markteinführung