CERTIFICATE OF COMPLIANCE

Certificate Number E23911

Report Reference E23911-19820217

Date 2021-January-28

Issued to: ABB Industrial Connections and Solutions, LLC

601 Shiloh Rd

Plano TX, 75074 US

This is to certify that representative samples of

AUTOMATIC TRANSFER SWITCHES FOR USE IN

EMERGENCY SYSTEMS

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 1008, Transfer Switches.

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.





CERTIFICATE OF COMPLIANCE

Certificate Number E23911

Report Reference E23911-19820217


Date 2021-January-28

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Type ZTS, ZTSD, ZTSCT, ZTG or ZTGD, CTS, CTSD, CTSCT, CTG, CTGD followed by H, K, or L followed by 80, 81, 100, 101, 120, or 121, followed by B, E or F, followed by C, CS, S or X, followed by -1 through -5, 7 through

9, 11 through 59 or 71 through 99, with or without additional suffixes. May include prefix letter K for export.

Alternative Nomenclature: Type Z, followed by S, followed by A, followed by O, D or C, followed by 080, 100 or 120, followed by B, C, D, E, F, J, K, L, M, or N, followed by S, X, or B, followed by X, 1, 2, 3, 4, 5, 6, 7, 8, 9, 0, A, B, C, D, E, F, G, H, I or J, followed by S, C, or D, followed by 1, 2, 3 or 5, followed by T or 1, followed by B, P, C, F, or M, followed by X, R, T, E, I, D, B, N, A, 1, 2, 3, 4, 5, 6, 7, or 8, followed by X, S, A, T, 1, 2, 3, or 4, followed by X, followed by 0 or C.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

