



NLRV.E121190 Motor Controllers, Manual

[Page Bottom](#)

Motor Controllers, Manual

[See General Information for Motor Controllers, Manual](#)

ABB STOTZ-KONTAKT GMBH
EPPELHEIMER STR 82
69123 HEIDELBERG, GERMANY

E121190

Investigated to ANSI/UL 60947-1 and ANSI/UL 60947-4-1A

Bus bar assemblies, Cat. No. PS3 or PS9, followed by -2, -3, -4, -5 or -6, followed by -0, -1 or -2; Cat. No. PS1, followed by -2, -3, -4, -5 or -6, followed by -0 or -1 -2, followed by -65, -100; Cat. Nos. PS3-2-2, PS3-4-2, PS9-2-3, PS9-4-2.

Bus bar assembly terminals, Cat. Nos. S1-M1-25, S1-M2-25, S1-M3-25, S1-M3-35, S3-M2, S3-M3, S4-M3, S4-M4.

[Last Updated](#) on 2012-01-27

[Questions?](#)

[Print this page](#)

[Notice of Disclaimer](#)

[Page Top](#)

© 2012 UL LLC

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Listed and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Designs and/or Listings (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2012 UL LLC".