





SACE Emax 2

Blocco antintroduzione - E2.2-E4.2-E6.2 IEC - UL
 Anti-racking-in lock - E2.2-E4.2-E6.2 IEC - UL
 Einfahrverriegelung - E2.2-E4.2-E6.2 IEC - UL
 Verrouillage anti-introduction - E2.2-E4.2-E6.2 IEC - UL
 Bloqueo antiintroducción - E2.2-E4.2-E6.2 IEC - UL

E2.2-E4.2-E6.2




	C	D	E	F	G	H
						
						
parte fissa fixed part festes Teil partie fixe parte fija	-	-	4	4	2	2
parte mobile moving part bewegliches Teil partie mobile parte móvil	2	2	4	-	-	-




MP-LEFT	E2.2 N-B-S							E2.2 H						
	02	08	10	12	16	20	25	08	10	12	16	20	25	
MATCH ALSO THE RIGHT SIDE														

MATCH ALSO THE RIGHT SIDE



FP-LEFT	E2.2 N-B-S							E2.2 H					
	02	08	10	12	16	20	25	08	10	12	16	20	25
	○	○	○	○	○	○	○	○	○	○	○	○	○
	○	○	○	○	○	○	⬛	⬛	⬛	⬛	⬛	⬛	⬛
	⬛	⬛	⬛	◻	◻	◻	○	○	○	⬛	⬛	⬛	◻
MATCH ALSO THE RIGHT SIDE													

MATCH ALSO THE RIGHT SIDE



For more information please contact:

ABB S.p.A.
 Via Pescaria, 5
 24123 Bergamo - Italy
 Phone: +39 035 395 111