MOTOR STARTING & SAFETY

Product change notification CP1 non-illuminated pushbuttons

PCN Details			
PCN Document No.	1SFC151071K0201	Date of PCN:	2022 Q4
PCN issued by:	Tuba-JianLin Kuang	PCN valid as of:	2022 Q4
Product Manager:	Pavlo Tkachenko	Obsolescence Date:	-
	Maggie-Huanwen Ao		
R&D Manager:	Doree-MingShi Fan	Change Date:	2022 Q4
	Jay-JieJun Lv		
Products impacted:	CP1 non-illuminated pushbuttons		
Impact on Form/Fit/Func-	[X] Form [] Fit [X]	Impact on reliabil-	[]Y [X]N
tion:	Fctn	ity:	

Dear Valued Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and our processes.

Description of Change

The structure on CP1 type non-illuminated pushbuttons will change due to the improvement of the production process. The details as shown on the image below.

Hooks on pushbutton sleeve will be change 90°.



abb.com/lowvoltage 1SFC151071K0201

Customer Impact of Change and Recommended Action

Impact on change 1: Customers need to pay attention for the change of the hooks if the hooks are used for positioning for installation in the applications

Impact on change 2: Caps cannot be removed for other color. Change will be visible if customer need to change bezel or 30mm adaptors, but product function & performance will not be affected.

Reason for Change

The change has been implemented to improve the production process.

Product Identification

See images above.

Customer acknowledgement

Customers are requested to acknowledge this notification within 10 days of its issue date. Lack of response with 30 days of PCN release will constitute an acceptance of the change.

Please contact ABB if you have any issues with this PCN or require additional information.

Customer:			
Name:	Title:	Phone:	
Email:			
Customer comments:			
Customer signature:	Date:		

abb.com/lowvoltage 1SFC151071K0201