Asea Brown Boveri, S.A. Fábrica NIESSEN Polígono industrial Aranguren nº 6 20180 Oiartzun, Gipuzkoa, Spain



DECLARATION OF ROHS COMPLIANCE

EU RoHS Directive 2011/65/EU and Amendment 2015/863/EU

| Substance/Substance Group Threshold | |
|--|-------------------------------------|
| Cadmium/Cadmium Compounds (Cd) | 0.01% at homogeneous material level |
| Lead/Lead Compounds (Pb) | 0.1% at homogeneous material level |
| Hexavalent chromium and Compounds (Cr6+) | 0.1% at homogeneous material level |
| Mercury/Mercury Compounds (Hg) | 0.1% at homogeneous material level |
| Polybrominated biphenyls (PBB) | 0.1% at homogeneous material level |
| Polybrominated diphenyl ethers (PBDE) | 0.1% at homogeneous material level |
| Bis(2-ethylhexyl) phthalate (DEHP) | 0.1% at homogeneous material level |
| Butyl benzyl phthalate (BBP) | 0.1% at homogeneous material level |
| Dibutyl phthalate (DBP) | 0.1% at homogeneous material level |
| Diisobutyl phthalate (DIBP) | 0.1% at homogeneous material level |

To whom it may concern,

We hereby send you information related to Article 4(1) of the EU RoHS (Restriction of Hazardous Substances) Directive (2011/65/EU). This communication applies to all Products sold (see table below) or otherwise placed on the market by **Asea Brown Boveri, S.A. Fábrica NIESSEN** prior to the signature date shown below.

| This declaration is valid for the following products | | | | |
|--|----------------------------|---------------------|--|--|
| Product number | Product description | Model number | | |
| 2CLA133120D1158 | Tecla RF solo 2 canales BA | 2CKA006730A0 055 | | |

If no such Products contain any of the above-referenced substances over the given threshold (regardless of exemption status), this option must be selected:

☑ Checking this box certifies that none of the Products referenced above contain any of the listed substances at a concentration over the given threshold limit by weight at the homogeneous material level.

Asea Brown Boveri, S.A. Fábrica NIESSEN Polígono industrial Aranguren nº 6 20180 Oiartzun, Gipuzkoa, Spain



OR, if any such Products contain any above-referenced substances over the given threshold level, the table below must be completed. Each Product below is deemed to contain one or more of the above-referenced above the noted threshold, either without exemption or with the listed exemption(s). Products not listed do not contain restricted substances over threshold.

RoHS List Status and applicable information

| Product(s) | RoHS Substance Group or Name | CAS Number (if available) | Exemption Number (if applicable) |
|------------|------------------------------|---------------------------|--|
| | | | |
| | | | |

Limitations

Asea Brown Boveri, S.A. Fábrica NIESSEN believes that the information it provides above is accurate. The provided information is based upon data obtained from ongoing due diligence concerning goods and materials provided by third party suppliers. Asea Brown Boveri, S.A. Fábrica NIESSEN provides such information "AS IS", without any express or implied warranty of any kind. Asea Brown Boveri, S.A. Fábrica NIESSEN reserves the right to update and modify this communication, as it believes necessary or appropriate.

Please do not hesitate to ask for further information.

Contact person: Eusebio Irurieta Title Product Compliance Manager

Email: eusebio.irurieta@es.abb.com Phone: +34 671 641 008

Eusebio Irurieta Zabala Product Compliance Manager Iñaki Lete Jauregui LBU Managing Director

ASEA BROWN BOVERI, S.A. Fábrica NIESSEN OIARTZUN - GIPUZKOA

Date of issue: 2022-10-21

Page 2 of 2