

ABB Automation Products Ladenburg	DCS800 Instruction how to upgrade DriveAP for DWL 2.95	
Dep.: APR/ADVP	Author: Thomas Vinz	Date: 15-Sep-15
	File: DCS800 Upgrade DriveAP for DWL 2.95 e a.docx	Page: 1 (1)

Types concerned

DCS800


Summary

Instruction how to upgrade DriveAP for DWL 2.95


Upgrade DriveAP for DWL 2.95

Make sure DWL is closed.


In Lotus Notes select *Save All Selected...* using a right click:



Choose *C:\Program Files (x86)\DriveWare\DriveWindow Light 2* and press OK:



Select Yes for all six files:



Start DWL.