

How to proceed in case of an error

Device cannot be programmed

GPG BUILDING AUTOMATION					
DocType:	Step-by-Step Guide	DocNr.	9AKK107492A6674	Revision:	Α
Department: BA Engineering		Author:	Engineering Team BA/DESTO		
System:	i-bus® KNX	Product:	KNX devices		
Page:	1/6	Date:	29 July 2019		



Liability Disclaimer:

This document serves the sole purpose of providing additional, technical information and possible application and use cases for the contained products and solutions. It **does not** replace the necessary technical documentation required for planning, installation and commissioning of the product. Technical details are subject to change without notice.

Despite checking that the contents of this document are consistent with the current versions of the related hard and software of the products mentioned within, deviations cannot be completely excluded. We therefore assume no liability for correctness. Necessary corrections will be introduced as and when new versions of the document are generated.

Introduction

There is a variety of reasons why a device cannot be programmed.

This document outlines these along with their solutions.

Objectives of the document

- Provide system integrators with suggestions for structured, independent troubleshooting that they can work through step by step.
- Provide practical tips and tricks for technical support.

Content

1. Checking if you can program a different bus device on the same line

To narrow down the cause of the fault, you need to establish if other devices on the same line can be programmed. If they can't, there may be a problem with the interface or line coupler.

Interface: Check settings in ETS

Line coupler: Check connection terminals on main line and line (transposed?)

Disconnect the lines from the line coupler and check each one separately

2. Checking the bus voltage/auxiliary voltage on the affected device

When you press the programming button, the red programming LED on a KNX device should light up. If it doesn't, check the bus voltage and auxiliary voltage (if there is one) with a multimeter.

If there is an operating voltage but the red LED does not light up, you can assume the device has a fault.

3. Checking the physical address

If the programming LED lights up when you press the programming button, you can use the ETS diagnostics function to check the device's physical address. Go to "Diagnostics – Physical addresses – Programming mode" for a list of all devices currently in programming mode (Fig. 1). Only the required device should appear in the diagnostics function. If the physical address does not match the one displayed in ETS, you need to amend it in the project or assign the device a new address.




Fig. 1 ETS diagnostics, devices in programming mode

In addition, make sure that each physical address is unique. If there are two devices with the same physical address, one of them will not be programmable because the system can't identify it as unique. The "Line Scan" diagnostics function in ETS is designed to establish whether there are two devices with the same physical address on one KNX line.

4. Reading out the application version loaded on a KNX device

The application version currently loaded on a KNX device is indicated in the device's information.

To read this out, select the relevant device in the topology and right-click to access "Info" and then "Device Info" (Fig. 2).




Fig. 2 ETS function, reading out device information

The screenshot below (Fig. 3) is an example of the device information for an ABB blind actuator.

Device Info of Device 1.1.12




Fig. 3 Device information

In the device information, make sure the load state is "Loaded" and the run state of the application is "Running".

Check the application version on the device to make sure it's up to date (see section 5).

5. Checking that the application version is up to date

- Select the product on the ABB i-bus KNX homepage
- Open the product information and select the "Downloads" tab.
- In Downloads you will find all the available documents for the product, including software information and the latest application.

Detailed information for: JRA/S2.230.2.1 This page contains technical data sheet, documents library and links to offering related to this product. Print... Print to Pdf... Print to Pdf... If you require any other information, please contact us using form located at the bottom of the page. Data Sheet Downloads Downloads for Blind Actuators 230 V AC Available documents: → Advanced search → Documents in all languages Show all (20) Software (.EXE) [XX] ABB i-bus Tool Summary: Version 1.9.37.0 ABB i-bus Tool supports system integrators during commissioning and service of KNX \dots (Show more) **≜** EXE Application note (2) Software - German, English, Spanish, French, Italian, Dutch, Polish, Russian 2019-02-25 - 23,33 MB Data sheet (2) Software Information (.PDF) [EN] JRA/S x.x.x.1 Declaration of conformity (3) Summary: No summary available Release note - English - 2018-07-26 - 0,02 MB . PDF Drawing (2) Product Manual (.PDF) [EN] JRA/S x.x.x.1 Manual (1) Summary: No summary available Manual - English - 2018-07-25 - 4,03 MB ₱ PDF Operating instruction (1) Selection table (.ZIP) [EN] Shading Control (InDesign file) Presentation (3)

Fig. 4 Product page and downloads, JRA/S x.x.x.1

Revision: A Page: 4/6 The application version is listed in device properties (Fig. 5).




Fig. 5 Device properties, ABB JRA/S 2.230.2.1

Note:

To convert an application, you can use the "ABB Copy Convert" app.



Fig. 6 ETS app, Update Copy Convert

As well as the latest application, you should always make sure you have the latest version of ETS installed.

This is shown bottom right on the ETS launch page.




Fig. 7 ETS launch page, version information

6. Are you programming all the lines?

In the topology, if the KNX interface is not on the same line as the device you wish to program, you run the risk of entering the wrong settings in the coupler, which can lead to errors.

In such cases, it's advisable to put the interface on the same line as the device you wish to program so that you can locate fault sources through a process of elimination.

If you are able to program a device in this configuration (without coupler), check the line coupler and its settings.

7. Separating a device

You can now check whether only one device is faulty, or whether there is an underlying fault in the system as a whole, by using a "Lab setup".

A lab setup consists of a KNX power supply, a KNX interface and the device you wish to program.

If you are able to program the device in this configuration, you can rule out a device fault.

References to other documents

- FAQ Home and Building Automation
- FAQ Reaction on error
- Engineering Guide Database

Page: