

BUILDING AND HOME AUTOMATION SOLUTIONS, 09/04/2020

Release Note Busch-ControlTouch®

Product name	Busch-ControlTouch [®] (<u>View</u> Website)
Product type	6136/APP-500
Order code	2CKA006136A0202
Current version	Firmware 1.3.2
Languages	EN, DE, NL, FR, IT, ES, RU, PL, SE, NO, FI, CN

ATTENTION:

All installed devices with a firmware older than version 1.3.0 <u>must</u> be updated, otherwise these devices will no longer work properly from May 2020 on. Claims arising from defects or damage due to a software version that is not up to date cannot be asserted.

How to check and update the current firmware version of your device:

- The customer should download the latest version of the iOS or Android App (Version 1.3.2)
- The customer should be in the same network as the ControlTouch
- When the app is opened, it automatically determines which firmware is installed on the ControlTouch
- If the installed firmware version is older than 1.3.0 you can update it directly out of the App (without interference of an installer)

ABB STOTZ-KONTAKT GmbH Eppelheimer Straße 82 69123 Heidelberg, Germany Telefon: +49 (0)6221 701 607 Telefax: +49 (0)6221 701 724 E-Mail: info.bje@de.abb.com abb.com/knx We reserve the right to make technical changes or modify the contents of this document without prior notice. With regard to purchase orders, the agreed particulars shall prevail. ABB AG does not accept any responsibility whatsoever for potential errors or possible lack of information in this document. We reserve all rights in this document and in the subject matter and illustrations contained therein. Any reproduction, disclosure to third parties or utilization of its contents – in whole or in parts – is forbidden without prior written consent of ABB AG. Copyright© 08 | 2017 ABB All rights reserved