

CERTIFICATE OF COMPLIANCE

Certificate Number 20150217-E327750
Report Reference E327750-20100424
Issue Date 2015-FEBRUARY-17

Issued to: ABB SPA ABB SACE DIV
DIN-RAIL
COMPONENTS AND WIRING ACCESSORIES
VIALE DELL'INDUSTRIA 18
20010 VITTUONE MI ITALY

This is to certify that representative samples of COMPONENT - FUSEHOLDERS, CARTRIDGE FUSE
Component Fuseholder, Series E90/32, 10x38 mm (midget)
fuse type, Fuseholders

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 4248-1, FUSEHOLDERS - PART 1: GENERAL
REQUIREMENTS
CSA C22.2 NO. 4248.1-07, FUSEHOLDERS - PART 1:
GENERAL REQUIREMENTS

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Recognized components are incomplete in certain constructional features or restricted in performance
capabilities and are intended for use as components of complete equipment submitted for investigation rather
than for direct separate installation in the field. The final acceptance of the component is dependent upon its
installation and use in complete equipment submitted to UL LLC.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at www.ul.com/contactus

