CERTIFICATE OF COMPLIANCE

 Certificate Number
 20181113-E225502

 Report Reference
 E225502-20130910

 Issue Date
 2018-NOVEMBER-13

Issued to: ABB Oy, Medium Voltage Products, Distribution Automation

MUOTTITIE 2A PO BOX 699

65101 VAASA FINLAND

This is to certify that PROTECTIVE RELAYS representative samples of See Addendum Page

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 508 and CSA C22.2 No. 14, Industrial Control

Equipment

Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC





CERTIFICATE OF COMPLIANCE

 Certificate Number
 20181113-E225502

 Report Reference
 E225502-20130910

 Issue Date
 2018-NOVEMBER-13

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Rack-mount Protective Relays, Model REF615R.

H or J or R, followed by W, followed by F, followed by A, followed by AA or AB, followed by A1 or AA, followed by NA, NB, AA, AB, AH, AK, AL, 33, NF, NG, FF, FG, FH, FK, or FL, followed by E, followed 1, 5 or 8, followed by A, B, C or D, followed by B or N, followed by A or N, followed by 1 or 2, followed by X followed by E.

Bambles

Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/

(UL)