

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190207-E345878  
**Report Reference** E345878-20190129  
**Issue Date** 2019-FEBRUARY-07

**Issued to:** ABB SPA ABB SACE DIV  
DIN-RAIL  
COMPONENTS AND WIRING ACCESSORIES  
VIALE DELL'INDUSTRIA 18  
20010 VITTUONE MI ITALY

**This certificate confirms that  
representative samples of** FUSEHOLDERS, PHOTOVOLTAIC  
PV Fuse Holder, Type E91/32 PV1500e

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 4248-1, Fuseholders - Part 1: General Requirements  
UL 4248-19, Fuseholders - Part 19: Photovoltaic

**Additional Information:** See the UL Online Certifications Directory at  
<https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

