ABB i-bus® KNX

**Software-Information** 

Product: Fan Coil Actuator

Type: FCA/S 1.1M

Current application program: Fan Coil Actuator/1.3a

\_\_\_\_\_

Software-Information to: Fan Coil Actuator/1.3a

from: 07/2013

1. General

The application is now available in 8 languages.

(German, English, French, Spanish, Italian, Russian, Dutch, Polish)

## ABB i-bus® KNX

## **Software-Information**

.....

Software-Information to: Fan Coil Actuator/1.3

from: 06/2011

1. Change:

Change of some texts.

2. <u>Status Valve position:</u>

If the status valve position = 1 bit, than work the parameter "object value" at

valve position > 0 inverts.

This was repaired.

3. <u>Incorrect Time Interval:</u>

The time intervals concerned begin in each case with n x 145,6355555s and

are 2,27s long. The adjusted time within this range is max. 2,27s long.

This was repaired

4. <u>Status objects "Valve Heating":</u>

HVAC-System: 2 Controls values/4 pipe

Status Valve Heating 1 Bit

Control value Heating = 0 --> Control value Cooling = 0 --> Control value Cooling = 0

The Status objects Valve Heating change the status, if the control value

Cooling "0".

This was repaired.

ABB i-bus® KNX	Software-Information	
Software-Information	to: from:	Fan Coil Actuator/1.2 06/2011
1. <u>General:</u>	The applic	cation program 1.2 has been used for internal use only.
Software-Information	to: from:	Fan Coil Actuator/1.1 06/2011
1. <u>General:</u>	The application program 1.1 has been used for internal use only.	
Software-Information	to: from:	Fan Coil Actuator/1.0 07/2008
1. <u>General:</u>		n program at time start of launch.