

CERTIFICATE OF COMPLIANCE

Certificate Number E48139
Report Reference E48139-20200715
Issue Date 2020-JULY-22

Issued to: ABB Stotz-Kontakt GmbH
Eppelheimer Str 82
69123 Heidelberg GERMANY

**This certificate confirms that
representative samples of**

AUXILIARY DEVICES

Auxiliary devices, electronic overload relays, open type,
consisting of:

Current Sensor Module: SCV10-40.1, SC10-40.1

Contactors Controller Module: SFM1-A11.1

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 60947-1 and CSA C22.2 No. 60947-1-13, Low Voltage
Switchgear and Controlgear, Part 1: General Rules
UL 60947-4-1 and CSA C22.2 No. 60947-4-1-14, Low
Voltage Switchgear and Controlgear, Part 4-1: Contactors
and Motor Starters, Electromechanical Contactors and
Motor-Starters.

Additional Information:

See the UL Online Certifications Directory at Fehler!
Linkreferenz ungültig. for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up
Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's
Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

