## CERTIFICATE OF COMPLIANCE

Certificate Number 20141124-E312527

Report Reference E312527-2014-11-20

Issue Date 2014-NOVEMBER-24

Issued to: ABB France

**ACTIVITE PROTECTION ET CONTROL** 

**3 RUE JEAN PERRIN** 

CS90009

69687 CHASSIEU CEDEX FRANCE

This is to certify that MOTOR CONTROLLERS, MAGNETIC

representative samples of SEE ADDENDUM PAGE

Have been investigated by UL in accordance with the

Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60947-1 & CSA C22.2 NO. 60947-1-13, LOW-

VOLTAGE SWITCHGEAR AND CONTROLGEAR UL 60947-4-1 & CSA C22.2 NO. 60947-4-1-14, LOW-VOLTAGE SWITCHGEAR AND CONTROLGEAR - PART

4-1: CONTACTORS AND MOTOR-STARTERS -

ELECTROMECHANICAL CONTACTORS AND MOTOR-

**STARTERS** 

Additional Information: See the UL Online Certifications Directory at

www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.

Bambles

Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <a href="https://www.ul.com/contactus">www.ul.com/contactus</a>



## CERTIFICATE OF COMPLIANCE

**Certificate Number** 20141124-E312527 E312527-2014-11-20 **Report Reference Issue Date** 2014-NOVEMBER-24

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Magnetic motor controllers. Across-the-line reversing and non-reversing contactors for use in industrial applications, 4 poles, open type -

Cat. Nos. AF40, AF52, AF80, followed by -22 or 40, may be followed by -00, -11, or -22, followed by 2 digits.

Cat. Nos. AF40R, AF52R, AF80R.

Cat. Nos. AF40M, AF52M, AF80M.

Cat. Nos. AF40N2, AF52N2, AF80N3.

Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licer contact a local UL Customer Service Representative at <a href="https://www.ul.com/contactus">www.ul.com/contactus</a>